ADATA S596
Firmware Install Tool
User Guide

Version 2.0

WARNING:

This firmware update is only valid for
ADATA S596 Solid State Drives

Before upgrade to F/W V2.0 version
Please make sure to upgrad your S596 to F/W V1.0

ADATA recommends that you back up your data

as a precaution before proceeding.

Table of Contents

1. Feature 4
2. QuickStart:..5
3. BIOS setup:..8
4. Upgrade firmware: 11
5. History: 13

Before you start you will need the following items:


- 1 x (preferably empty) USB flash drive
- Downloaded version of the firmware update program ADATA S596 Firmware Update Tool
– please find the files on http://www.adata.com.tw/?action=product_download&cid=3&piid=35

1. Feature


- Auto makes an USB device bootable.
- Auto copy ISP tool into the bootable device.


2. Quick Start:

- Insert an USB device.
- Execute the tool (JMISPInst) and press the “Start” button.



威剛科技股份有限公司 台北縣中和市連城路258號2樓
ADATA Technology Co., ltd. Tel (886) 2 8228-0886 Fax (886) 2 8228-0887 2F., No.258, Lian Cheng Rd., Chung Ho, Taipei 235, Taiwan (R.O.C.)



SSD upgrade tool installer 1.0
Device
USB Flash Disk
Jmispinst
WARNING! ALL DATA ON THE DEVICE WILL BE LOST!
Do you rellay want to proceed with the step?
是(Y)
否(N)
Start
Close




威剛科技股份有限公司　台北縣中和市連城路258號2樓
ADATA Technology Co., ltd.　Tel (886) 2 8228-0886　Fax (886) 2 8228-0887　2F., No.258, Lian Cheng Rd., Chung Ho, Taipei 235, Taiwan (R.O.C.)


3. BIOS setup:

- Change Boot Device Priority






- Configure SATA as “IDE mode”
-
- Save and exist


BIOS SETUP UTILITY
Boot
Boot Device Priority
1st Boot Device
[USB:USB]
2nd Boot Device
[1st FLOPPY DRIVE]
3rd Boot Device
[ATAPI CD-ROM]
Specifies the boot sequence from the available devices.
A device enclosed in parenthesis has been
Save configuration changes and exit now?
[Ok]
[Cancel]
Select Item
Change Option
F1 General Help
F10 Save and Exit
ESC Exit
American Megatrends, Inc.


4. Upgrade firmware:

- Please “Y” to upgrade firmware automatically.
- Reboot after upgrade firmware successfully.



威剛科技股份有限公司 台北縣中和市連城路258號2樓

ADATA Technology Co., ltd. Tel (886) 2 8228-0886 Fax (886) 2 8228-0887 2F., No.258, Lian Cheng Rd., Chung Ho, Taipei 235, Taiwan (R.O.C.)



Congratulations, you have completed your firmware update.

Enjoy.

5. History:

Version	Date	Remark
1.0	10/08/18	Upgrade firmware 091222 firmware to 100113
2.0	10/09/28	Upgrade firmware to 100312